Beng !

25X1A

25X1A-

SECONOR INCOMINA

May 26, 1964

	SUBJECT: Cost estimate for completion of Chip Cutter/
25X1A	

Cantlemen:

As we advised by our letter of April 20, 1964 funds have been depleted on the work order for one (1) Chip Cutter/Viewer.

The primary reason for this job running over the estimated cost was that the job was halted at customer request when the layouts had been nearly completed. After a delay of more then two mouths we were asked to resume work. However, the designer who had done the initial work was committed on other work and another designer had to take over on the job. In addition several features were added to the design which were not anticipated in our original proposal.

The unit has been coupleted through the chip outser head, but without the light table section or transfer carriage.

It is estimated that the unit can be put into working order for evaluating our chip cutting technique for an additional cost of \_\_\_\_\_\_\_\_ Approxi- 25X1A mately \_\_\_\_\_\_ of the original funds are evailable. We estimate the unit can be completed in another 200 hours of labor, or \_\_\_\_\_\_ plus an \_\_\_\_\_\_ 25X1A additional \_\_\_\_\_\_ of material, consisting mainly of light sources, dissert coutrol bearings, bearing rails and reel brackets.

Please advise us at your carliest convenience if these additional funds will be made symilable so that this work can be completed. We estimate it will require about six weeks to complete the work after authorization.

Vine	President
1.00	그 그 그 그 그 그 그 그 그 그 그 그 그 그 그 그 그 그 그
1.00	

25X1A

25X1A

**Declass Review by NIMA/DOD** 

Approved For Release 2002/06/17 : CIA-RDP78B04747A000900160013-2

17 June 1964		
	<u>.</u>	25X1A
1 88 for the "they Cutter"	Information for a	
		25X1A
datid 25X1A	Work Order nr.	
te	Original cost es	
al		
25X1A		
ther were given to tony	MFR: The original of the above 26 May is this OM. long will write a yearn moving.	25X1A